







Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Резервни делови / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu

XX = AA, GN, ...

Pos.	Part No.
1	A 861 405 XX
2	B 961 373 XX
3	B 961 374 NU
4	A 861 181 NU
5	A 861 156 NU
6	A 960 183 NU
7	A 962 359 NU
8	E 960 059 NU
9	B 961 383 XX
10	A 964 520 NU
11	B 960 900 XX
12	A 961 172 NU
13	A 961 230 XX



P 0,3 MPa 3 bar	T 50°C 65°C 85°C	T 15°C 15°C 15°C	0	1	2	3	4	5
			°C	°C	°C	°C	°C	°C
	50°C	15°C	50	49	44	40	35	33
	65°C	15°C	65	63	57	50	44	40
	85°C	15°C	85	83	74	64	56	50




Ideal Standard

CONNECT AIR

A 7021 .. A 7024 .. A 7053 .. A 7055 ..







0221 / A 868 383
 Made in Germany



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com





	P bar	0,5		5		Q (3 bar)
	T °C		MAX. 85	65		l/min
				40		5